

OSID-Range - Erratum

February 2021

Affected Products

Conventional: OSI-R, OSI-RA, OSI-R-SS, OSI-RA-SS

Intelligent: OSI-RI-SS, OSI-RIA-SS, OSI-RI-FL, FS-OSI-RI, FS-OSI-RIA, OSI-RI-FH, OSI-RI-GW, OSI-RI-SK

Problem

Wiring drawing errors in the Product Guides and Quick Start Guides of the concerned products has been discovered. Specifically, a jumper position switch between isolator settings and the heater setting in the wiring diagrams.


The field correction, if the jumper(s) were applied at all, can simply be executed at a next service call.

Alarm signaling and fault signaling in the field were never compromised!

A corrective action on Product Guides and Quick Start Guides is already in place.

Solution

Wrong jumper settings:



Correct jumper settings:

