

End of Life Notice

Product End of Life Notice: OSI-45 February 19, 2017

The OSID open area imaging smoke detectors continue to offer a unique and powerful beam detection solution serving a wide range of markets and applications.

Please be advised that OSI-45 detectors will be discontinued due to the continued unavailability of a unique component.

On 6/6/2016 customers were informed that Xtralis was experiencing supply issues with the OSI-45 product. Xtralis can no longer manufacture and supply OSI-45 imagers because the lens supplier is no longer offering the 45° lenses. This is beyond Xtralis' control and although Xtralis has been working closely with various suppliers to find solutions and/or alternatives, Xtralis has not been able to source a new lens that offers the same or an acceptable performance. This is principally due to the fact that the requirements for UV/IR performance are much more demanding than for visible light.

As a result Xtralis has decided to withdraw, with immediate effect, the OSI-45 from the global OSID offering. All sales material and collateral are updated to reflect this change.

Please note that there is globally no more stock of the OSI-45, so all new offers will need to substitute the OSI-45 with either an OSI-10 or OSI-90 solution.

Outstanding orders for the OSI-45, can only be fulfilled with the alternative OSI-10 and/or OSI-90 solution.

Discontinued Part Number	Description
OSI-45	Imager - 38° coverage

Info/Questions:

For additional information and questions, contact your Xtralis Sales Representative.