



# CRITICAL PRODUCT SECURITY INFORMATION FOR INSTALLERS, COMMISSIONING ENGINEERS AND USERS

---

## VESDA VLI

WARNING: Failure to comply with the requirements below exposes the system to malicious interference which could disable alarm reporting

### Commissioning Requirements

- All VESDAnet wiring and connection ports must be secured against unauthorized access.
- The Ethernet port must ONLY be connected to networks which are secure and physically or logically separate from business IT infrastructure.
- VESDA devices including HLIs must not be accessible from the Internet. Any provision of remote access to VESDA devices must be subjected to a full cyber security risk assessment and regular review.
- Restrict access to HLI devices to authorized personnel only.
- Default PIN codes must be changed as part of the initial configuration.

### System Maintenance Requirements

- The USB port is intended only for configuration and maintenance by authorized personnel.
- If a detector requires firmware upgrade, ensure that the upgrade package is genuine and obtained directly from Xtralis.